Attorney Docket No. 134

IE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Saori MIYATA et al.

Application No.: 10/665,408

ATTENTION

Confirmation No.: 4402

CERTIFICATE OF CORRECTION

Filed: September 22, 2003

BRANCH

U.S. Patent No.: 6,947,872

Batch No.:

Issued: September 20, 2005

For:

REMOTE MAINTENANCE REPEATER AND INTERNETWORK CONNECTOR

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents PO Box 1450 Alexandria, VA 22313-1450 of Correction

Sir:

Patentees respectfully request that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistakes shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STAAS & HALSEY LLP

Date: ____4-20-06

distration No. 28.607

1201 New York Ave, N.W., 7th Floor

Washington, D.C. 20005 Telephone: (202) 434-1500

Facsimile: (202) 434-1501

PTO/SB/ 44 (08-00)
Approved for use through 09/30/2000. OMB 0651-0033
U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE
Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO: 6,947,872

DATED: September 20, 2005

INVENTOR(S): Saori MIYATA et al.

Column 15, line 10, delete "network" and insert --networks--

Column 15, line 36, after "connector" insert --being connected to a monitoring apparatus that monitors and remotely maintains the internetwork connector--

MAILING ADDRESS OF SENDER:

STAAS & HALSEY LLP 1201 New York Ave., N.W. 7th Floor Washington, DC 20005

PATENT NO. 6,947,872

No. of add'l copies @ 50¢ per page